Wednesday, 9/13/2006 4:14:24 PM Date: _User: Kim Johnston **Process Sheet** : 206B STEP ASSY, RH Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : 28504A **Estimate Number** : 11699 : HA : D2721042 Part Number P.O. Number : D2721 REV C S.O. No. : NA This Issue : 9/13/2006 **Drawing Number** Prsht Rev. : N/A **Project Number** : LARGE FAB ASSY : C First Issue **Drawing Revision** : WM : 26714A Material **Previous Run** Each 3 Um: : 10/5/2006 Qty: **Due Date** Written By Checked & Approved By 06-01-06 JLM Comment Per Ecn 766 **Additional Product** Job Number: Description: **Machine Or Operation:** Seq. #: D2622120C 1.0 Extrusion Comment: Qty.: 1.0000 Each(s)/Unit Total: 3.0000 Each(s) Batch: 3282/5 = 3 Description Qty Part# Extrusion 1 D2622-120C Check Material for any Dents or Defects LARGE FABRICATION RESOURCE 1 2.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 06.10.12 Cut D2721-2 using D2622 extrusion as per Dwg D2721 Deburr and bevel ends for welding 3.0 D2734 206 Step Endplate 2.0000 Each(s)/Unit Comment: Qty.: Total: 6.0000 Each(s) 206 Step Endplate Pick: Description Qty Part Number 2 D2734 End Cap 4.0 D34611 Comment: Qty.: 1.0000 Each(s)/Unit Total: 3.0000 Each(s) 206 Step Lug Pick: Description Qty Part Number

D3461-1

Plate

Form: rprocess

Dart Aerospace I	Lta
------------------	-----

Dart Ae	rospace	e Ltd						~		
W/O:	WORK ORDER CI STEP PROCEDURE CHANGE PAR #: Fault Category: WORK ORDER NON-CONFOUNT Corrective Action Initial Chief Eng Chief Eng					}				
DATE		Р	ROCEDURE CI		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							· 			
Part No	:	PAR #:	Fault Ca	itegory:	ļ N	ICR: Yes	No DQ	A :	_ Date: _	
						QA: N	/C Close	d:	_ Date: _	
NCR:			WORK OR	DER NON-CONFO	RMAN	CE (NCR	(1)			
DATE	OTED	Description of NC				Section B		ation	Approval	Approval
DATE	SIEP			Action Descrip Chief Eng	tion	Sign & Date	Secti		Chief Eng	Approval QC Inspector
							aut			
								\$		
									i	
									•	
	+ +			 	1					

Date: Wednesday, 9/13/2006 4:14:24 PM User: Kim Johnston **Process Sheet** Drawing Name: 206B STEP ASSY, RH Customer: CU-DAR001 Dart Helicopters Services Part Number: D2721042 Job Number: 28504A Job Number: Sea. #: **Machine Or Operation:** Description: D34613 PLATE 5.0 Comment: Qtv.: 1.0000 Each(s)/Unit 3.0000 Each(s) Total: Pick: Description Batch Qtv Part Number 3263/2 = 3D3461-3 Plate PLATE 6.0 D34615 Comment: Qty.: 1.0000 Each(s)/Unit Total: 3.0000 Each(s) Pick: Description Qtv Part Number D3461-5 Plate 7.0 D34617 3.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Pick: Description Qty Part Number D3461-7 Plate LARGE FABRICATION RESOURCE 1 8.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 followed by Jig DT 1.06.10.12 Weld end cap (One End Only) and lugs as per Dwg D2721 using Jig DT l. E. 06.10-12 3 AL Rod AMA M19612 E M 18838 Grind end cap welds flush WELD INSPECTION 9.0 QC5/9 **Comment: WELD INSPECTION**

Dart Aerospace Lt	[a
--------------------------	----

											
W/O:			V	NORK O	RDER CH	ANGES					-
DATE	STEP	PRO	PROCEDURE CHANGE						Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
										·	
											,
·											
Part No	•	PAR #:	Fault Ca	ntegory: _		NC	R: Yes	No DQ	A :	Date:	
							QA: N	I/C Close	d:	_ Date: _	
NCR:		\	WORK OR	DER NO	N-CONFO	RMANCI	E (NCF	₹)			
DATE	STEP	Description of NC			ive Action	Section B		Verific	ation	Approval	Approval
	Section A		Initial Action		ction Descrip Chief Eng	tion Sign & Date		Section C		Chief Eng	QC Inspector
					- -		1 min				
					·						
		•									
4. **											
				-							


Date: Wednesday, 9/13/2006 4:14:25 PM User: Kim Johnston Drawing Name: 206B STEP ASSY, RH Customer: CU-DAR001 Dart Helicopters Services Job Number: 28504A Part Number: D2721042 Job Number: Seq. #: Machine Or Operation: Description: HAND FINISHING RESOURCE #1 10.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 11.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION LARGE FABRICATION RESOURCE 1 12.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 Inspect for foreign object per QSI 024 followed by Jig DT Weld Remaining end cap as per Dwg D2721 using Jig DT Batch: M18833 AL Rod Grind End Cap Welds Flush WELD INSPECTION 13.0 QC5/9 Comment: WELD INSPECTION HAND FINISHING HAND FINISHING RESOURCE #1 14.0 Comment: HAND FINISHING RESOURCE #1 Touch Up Alodine POWDER COATING 15.0 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 16.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

Dart Ae	rospace	Ltd								
W/O:			W	ORK ORDER CH	ANGES			·- ,		
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NC) Date:	
NCR:			WORK ORD	ER NON-CONFO	RMANCE					
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Descrip Chief Eng	Section B tion	Sign & Date	Verifica Sectio		Approval Chief Eng	Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·										

Date: Wednesday, 9/13/2006 4:14:25 PM User: Kim Johnston **Process Sheet** Drawing Name: 206B STEP ASSY, RH Customer: CU-DAR001 Dart Helicopters Services Part Number: D2721042 Job Number: 28504A Job Number: Seq. #: Description: **Machine Or Operation:** HAND FINISHING1 HAND FINISHING RESOURCE #1 17.0 Comment: Wing Walk as per Dwg D2721 and QSI 00 5 4.4 18.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERS Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE#1 PACKAGING 1 19.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: FINAL INSPECTION/W/O RELEASE 20.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE L 06.00.20 Job Completion

Dart	Aer	ospa	ace	Ltd
------	-----	------	-----	-----

Dart Ae	rospace	e Ltd								
W/O:			V	VORK ORDER CH	ANGES		-			
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		`.	15.							
_			•							
Part No:		PAR #:	Fault Ca	tegory:	NC	R: Yes N	No DQA	\ :	_ Date: _	
						QA: N/	C Closed	l:	_ Date:	
NCR:			WORK OR	DER NON-CONFO	RMANCE	E (NCR)				
DATE	STEP	Description of NC	Corrective Action		Section B		Verification		Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Date	Section		Chief Eng	QC Inspector
				ļ				,		
					l					
							}			
								,		




Each

Wednesday, 9/13/2006 4:14:07 PM Kim Johnston **Process Sheet** : 206 A/B STEP ASSEMBLY RH : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Job Number : 28504 : 11115 **Estimate Number** : D206628012 : NA **Part Number** P.O. Number : N/A **Drawing Number** : 9/13/2006 This Issue : N/A **Project Number** Prsht Rev. : LARGE FAB ASSY : N/A Type **Drawing Revision** First Issue : MM : 26714 Material Previous Run **Due Date** : 10/5/2006 Qty: 3 Um: Written By Checked & Approved By As Per Ecn 766 06-01-06 JLM Comment **Additional Product** Job Number: **Description: Machine Or Operation:** Seq. #: DOCUMENT CONTROL DC 1.0 Comment: DOCUMENT CONTROL Photocopy blue file and type labels as per PPP D206-628-012 CHG 002 206B STEP ASSY, RH 28504A 2.0 Comment: Sub-Component SUB-ASSEMBLY 206B STEP ASSY, RH D2721-042 B B28507A PACKAGING RESOURCE #1 PACKAGING 1 3.0 Comment: PACKAGING RESOURCE #1 Pick Packing Kit 4.0 D27311



Comment: Qty.: 2.0000 Each(s)/Unit Total: 6.0000 Each(s) Pick:



Description

5.0 D27317





Comment: Qty.: 2.0000 Each(s)/Unit Total: 6.0000 Each(s)

Pick:

Qty Part Number 2 D2731-7 Mounting Lug

Description

Dart Ae	rospace	Ltd								
W/O:			WC	ORK ORDER CH	ANGES					
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NC	R: Yes	No DQ	A:	Date:	
									Date: _	
NCR:			WORK ORDI	ER NON-CONFO	RMANCE	(NCR	2)			
		Description of NC		Corrective Action	Section B		Verification		A = = = = = 1	Annroyal
DATE	STEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Section C			Approval Chief Eng	Approval QC Inspector
										

Wednesday, 9/13/2006 4:14:07 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: 206 A/B STEP ASSEMBLY RH Customer: CU-DAR001 Dart Helicopters Services Part Number: D206628012 Job Number: 28504 Job Number: Description: Seq. #: **Machine Or Operation:** Abrasion Strip 6.0 D2856400 1.1708 f(s)/Unit Total: 3.5123 f(s) Comment: Qty.: Pick: Description Batch Qty Part# B28258 2 D2856-400 6.9" Abrasion Strip D2856400 Abrasion Strip 7.0 Comment: Qty.: 0.5460 f(s)/Unit Total: 1.6380 f(s) Pick: Description Part # Qty 2 D2856-400 6.25" Abrasion Strip D3394041 2.0000 Each(s)/Unit Total: 6.0000 Each(s) Comment: Qty.: Pick: Description Qty Part Number 2 D3394-041 LUG ASS,Y <u>B2546</u>7 2.0000 Each(s)/Unit Total: 6.0000 Each(s) Comment: Qty.: Batch 485 > April Bolt Pick: Description Qty Part Number 2 D3394-043 LUG ASS,Y _ 10.0 AN415A 4.0000 Each(s)/Unit Total: 12.0000 Each(s) Comment: Qty.: Pick: Batch
M/22039_
Bolt Qty Part Number Description 4 AN4-15A 11.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 12.0000 Each(s) Pick: M/20 773 -Description **Qty Part Number** 4 AN4-11A Bolt Form: rprocess

Page 2

Dart Ae	rospace	e Ltd			i					
W/O:			WC	ORK ORDER CH	ANGES					
DATE	STEP	PRO		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					1					
Part No	:	PAR #:	Fault Cate	gory:	NC	R: Yes	DQ O	A: 🔎	Date: <u>Ø</u>	6/18/24
				İ	Į.				Date:	•
NCR:		V	VORK ORDI	ER NON-CONFO	RMANCE	(NCR)			
5475	OTED	Description of NC		Corrective Action	Section B	Verification		Annroyal	Annroval	
DATE	STEP Description of NC Section A	Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Date	gn & Section C		Approval Chief Eng	Approval QC Inspector
								·· ·		
						:				

Date: We	ednesday, 9/13/2006 4:14:0	07 PM	1 1	
4	n Johnston		ss Sheet	
Customer	: CU-DAR001 Dart Helico	opters Services	Drawing Name: 206 A/B STEP ASSEMBLY RH	
Job Number	r: 28504		Part Number: D206628012	
Job Number:				
Seq. #:	Machine Or Operation	:	Description :	
12,0	AN412A	Bolt I II I II I	HARRI MILITAL	
Comn	nent: Qty.: 4.0000 Eac	ch(s)/Unit Total: 12.0000 Each	h(s)	
	Pick: Qty Part Number	Description Batch		
	4 AN4-12A	Bolt <u>M10/390</u>		
13.0	AN960JD416	Washer		
Comm	nent: Qty.: 12.0000 Ea	ch(s)/Unit Total: 36.0000 Each	neolegimes stoch sort 31.50	
	Pick: Qty Part Number	Description Batch	Passet of	
Č	12 AN960JD416	Washer <u>M 1918</u> 5	surt 31.50	<u>.</u>
14.0	MS21042L4	Nut		
Comm	nent: Qty.: 12.0000 Ea	ch(s)/Unit Total: 36.0000 Each	rh(s)	
	Qty Part Number	Description Batch	09 / / /	6
	12 MS21042L4	Nut (or MS21042-4) 190		13)
15.0	QC4	INSPECT 10	00% KITS FOR COMPLETENESS	
	packaging 1	TS FOR COMPLETENESS	(18 04/10/23 (3) G RESOURCE #1	
16.0	PACKAGING 1	PACING	O RESCONCE #1	
Comm	ent: PACKAGING RESC		40	
	Location:	r shipping as per PPP D206-628-01:		
	PPP Rev:		/Wallo /24 /3)	
17.0	QC21	FINAL INSPE	PECFION/W/O RELEASE	3
Comm	ent: FINAL INSPECTION	N/W/O RELEASE	D (0010) 2.	1
Job Completion			W Dle. 10.24	

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES											
DATE	STEP	PR	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
	:												
Part No	:	PAR #:	Fault Cate	gory:	N	NCR: Yes	No DQ/	A :	Date:				
						QA: N	/C Closed	d:	_ Date: _				
NCR:			WORK ORDE	R NON-CONFO	RMAN	CE (NCF	R)						
DATE	STEP	Description of NC	Corrective Action		Section E		Verification		Approval	Approval			
DATE		STEP Section A	Initial Chief Eng	Action Descrip	tion ———	Sign 8 Date	Section		Chief Eng	QC Inspector			
				-									
								,					
						:							
													